

HL-WB ASSEMBLY INSTRUCTIONS

PART LIST

- 1-TOP MAST
- 4-HEXAGON BOLT
- 1-BOTTOM MAST
- 12-SELF-TAPPING SEREWS
- 3-CONNECTING BAR
- 4-LEVELER

BOLTS ARE SCREWED
IN PLACE

