

AK-003 ASSEMBLY INSTRUCTIONS

PART LIST

- 1-TOP PIPE
- 2-T FRAME
- 1-MAST
- 12-WASHER
- 12-SPRING WASHER
- 12-HEXAGON BOLT
- 1-BOTTOM PIPE
- 2-WASHER
- 2-SPRING WASHER
- 2-HEX BOLT
- 2-LOCK CASTER
- 2-NOT LOCK CASTER

BOLTS ARE SCREWED
IN PLACE

